203.10 - Reference Points (solid forms)

These moderate purity SRMs are for use in preparing reference point devices and for calibrating thermometers, thermocouples and other temperature measuring devices.

Technical Contact: gregory strouse@nist gov

PLEASE NOTE: The tables are presented to facilitate comparisons among a family of materials to help customers select the best SRM for their needs. For specific values and uncertainties, the certificate is the only official source.

SRM	45d	49e	742
Description	Cu Freezing Point	Lead Freezing Point	Alumina (Reference Point)
Unit of Issue	(450 g)	(600 g)	(10 g)
Temperature (in oC)	1084.8	327.45	2052